Е

July 6, 2009 7:28:00 AM

Item ID:

D3188-5

**Revision ID:** 

Spacepod Body Item Name:

**Start Date:** 

7/07/09

Start Qty: 1.00

Req'd Qty: 1.00

Accept



Setup Start



Stop

Required Date: 7/15/09 Reference:

**Approvals:** 

QC:

**Process Plan:** 

Date: Date: Tooling:

SPC (Y/N):

Date:

**Cust Item ID:** 

**Customer:** 

Date:

Draw

Rev.

Plan

Code

Run Start

Reject

Qty

Accept

Qty



Insp.

Stamp

Stop

Reject

Number

Sequence ID/ **Work Center ID**  **Operation** Description

**Draw Nbr** 

**Revision Nbr** 

D3188 Rev E

QC

Quality Control

Memo

Memo

Memo

QC6- Inspect dimensions to drawing

Check for void spot and pins.

5 09/07/13

0.00

0.00

110

Packaging

Packaging

120

QC

Quality Control

QC21- Final Inspection - Work Order Release

Identify as per dwg & Stock Location:

0.00

0.00

09107114 AJ

Draw Set Up/ Number **Run Hours** 

## **Picklist Print**

July 6, 2009 7:27:59 AM

Work Order ID: 45696

Parent Item:

D3188-5RevE

Parent Item Name: Spacepod Body

SPACEPOD BODY LH

Comments:



**Start Date:** 7/07/09

Required Date: 7/15/09

Start Qty: 1.00

Required Qty: 1.00

	Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
/	D3188-1MRevE		Manufactured	No			100	Each	0.0000	1.0000			
/													

Tuesday, 10/02/2009 3:06:43 PM

Julie Dawson Űser

## **Process Sheet**

Customer

: CU-DAR001 Dart Helicopters Services

: 45696

Job Number **Estimate Number** 

: 13782

P.O. Number

Prsht Rev.

First Issue

Comment

This Issue

: 10/02/2009

: //

: NC

Type

S.O. No. :

Part Number

**Drawing Name** 

: D31885

: SPACEPOD BODY LH

**Drawing Number** 

Project Number

: N/A : E

**Drawing Revision** 

Material **Due Date** 

: 28/02/2009

: D3188 REV.E

Qty:

1 Um: Each

Written By Checked & Approved By

**Previous Run** 

: Est Rev:A 09-02-05

: PURCHASED PARTS

New Issue DD verified by:EC

**Additional Product** 

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0 45696A

QC6

SPACEPOD BODY LH

Comment: Sub-Component SPACEPOD BODY LI

1 x D3188-1M Batch

0907/3

2.0

DIMENSIONAL CHECK



Comment: DIMENSIONAL CHECK

Inspect dimensions as per Dwg D3188 . Visual inspection. Check for void spot and pins.

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location:

QC21

FINAL INSPECTION/W/O RELEASE





Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



Dart	Aeros	space	Ltd
------	-------	-------	-----

	•												
W/O:		WORK ORDER CHANGES											
DATE	STEP	PR	PROCEDURE CHANGE				Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
				٠.									
Part No:		PAR #:	gory:	NCR: Ye	es No <b>D</b> C	DQA: Date:							
	Re	solution:	Dispositio	n:	QA: N/C	QA: N/C Closed:			Date:				
NCR:			WORK ORD	ER NON-CONFORM	ANCE (N	CR)							
DATE	STEP	Description of NC			ction B	Verif	ication		Approvai				
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng			tion C		QC Inspector				
					1	1							

NOTE: Date & initial all entries